

5. Useful Forms/ Check List – Samples

5.4 Recommended List of Personal Protective Equipment

Job	Potential Hazard	Respirator and Clothing
Testing and commissioning	Aerosol	Half face piece, capable of filtering smaller than 5µm particulates, ordinary work clothing
Inspection	Aerosol	Half face piece, capable of filtering smaller than 5µm particulates, ordinary work clothing
Water Sampling	Aerosol	Half face piece, capable of filtering smaller than 5µm particulates, ordinary work clothings
High pressure spraying	Aerosol	Respirator as above, waterproof overalls, gloves, boots, goggles or face shield
Chemical treatment with sodium hypochlorite solution in ventilated space	Spray mist and very low concentration chlorine	Half face piece, capable of filtering smaller than 5µm particulates, ordinary work clothing
As above, in confined space	Unknown chlorine concentration, high mist, possible lack of oxygen	To comply with the requirement under the Factories and Industrial undertakings (Confined Spaces) Regulation